

FIG. 1




Fig. 1

✓

FIG. 2




Fig. 2




Fig. 3

✓

FIG. 4




Fig. 4




Fig. 5

FIG. 6




Fig. 6




Fig. 7

✓




Fig. 8

✓

1001445-1230




Fig. 9

✓

10017455-121301
FOE127 5542T001

901




Fig. 10

✓

10017455-121301




Fig. 11

✓

FIG. 12




Fig. 12

2

10017455-121301




Fig. 13

10017435-131301




Fig. 14

10017455-121304




Fig. 15

✓





Fig. 16 a



1007455-1007




Fig. 18a




Fig. 18b




Fig. 19a






Fig. 19b

✓

1950年12月15日



10017455-121301




Fig. 21a




Fig. 21b




Fig. 22b







Fig. 22C



10017455-41301



10017455-1304



23
Fig. 23a

2

10017455, 121301




Fig. 24a

10017455 542FOOT




Fig. 24b




Fig. 25a







Fig. 25b






10017455-121301


2801
↓



Fig. 28a





2801



Fig. 28b





1001455-14301








Fig 32a




Fig 32b




Fig. 33d




Fig. 33a




Fig. 33b




Fig. 33c




Fig. 34a





Fig. 34b

TOELET "SHZT00T"







Fig. 36

10017455-13101



FOET 21 SH 21001




Fig. 38